## FORD 5R110/ TORQSHIFT Value Added Quality Improvements

## from JASPER

ICCIIA .	/ Concern

## **JASPER Solution:**

Converter lockup lining failure Shudder

 2003 – 2008: Installation of NEW forged/billet converter front cover to prevent flexing at the studs and to ensure full contact of the lockup piston with the front cover to prevent shudder.

Line pressure instability

- 100% reaming and vacuum testing of the pressure regulator valve bore for consistent line pressure.
- Replacement of all early-style pressure regulator valves to the late style to maintain consistent line pressure.

Pump wear, front seal leaks and fluid contamination

- Pump gears are 100% Phos dipped to prevent dry start-up and to keep gears from seizing with the pump.
- Installation of a machine-in-place bushing in the pump housing to provide correct alignment between the pump bushing and converter hub.

Hub breaks out of coast drum causing "no pull" situation

 2009 and up: Hub is welded into the coast drum to prevent the hub from breaking out of the drum.

Snap ring rotation

• Early-style low/reverse snap ring is updated to the latest style to keep ring from rotating in the case.

Lubrication circuit

 2003 – 2007: Low/reverse diode is replaced and updated to the late style to prevent side load (JASPER uses a two-lock strut vs. a one-lock strut).
 The low/reverse diode is prone to failure if starved for lube oil.

Clutch and unit failure

- JASPER updates the early-style spring retainer for the low/reverse clutch to prevent the snap ring from popping off resulting in metal contamination, clutch failure and unit failure.
- JASPER restakes all early-style low/reverse planetary pinion pins with 12 tons of pressure to prevent pinion pin walkout.
- 100% remanufactured low/reverse clutch on 2008 2011 one-piece planetary to ensure long life.

Shift solenoid issues

 100% replacement of early-style BA and CA solenoids with updated, more robust BB and AB solenoids.

Shift quality, leaks and range sensor operation

 100% dynamometer tested for proper gear ratios, line pressure, cooler pressure and flow, noise and correct MLPS switch voltage.

3 Year/100,000 Mile
Nationwide
Parts & Labor Warranty



Remanufactured in the U.S.A.

Full warranty disclosure available at www.jasperengines.com or upon request.

Specifications subject to change without notice.

815 Wernsing Road • P.O. Box 650 • Jasper, IN 47547-0650 (800) 827-7455 • Fax (812) 634-1820 • www.jasperengines.com

AD-E06-86-55320, Rev: 5, Rev Date: 12/29/14